


April 16, 2011

To : UNISIS CORP.JAPAN



KAKEN Co., Ltd.
1044, Hori, Mito, Ibaraki
310-0903, Japan
Phone +81-29-227-4485
Fax +81-29-227-4485

Certificate

Radioactivity Measurement

Sample description:

Puncture Needles LotNo.11B Before the earthquake

Nuclide	Result (Bq/kg)	Detection Limit (Bq/kg)
Iodine-131	Not detected	20
Caesium-134	Not detected	10
Caesium-137	Not detected	10
Caesium-136	Not detected	11

Method:

Gamma ray spectrometry

Y.HANAMOTO

Reviewed by

April 16, 2011

To : UNISIS CORP.JAPAN



KAKEN Co., Ltd.
1044, Hori, Mito, Ibaraki
310-0903, Japan
Phone +81-29-227-4485
Fax +81-29-227-4485

Certificate

Radioactivity Measurement

Sample description:

Puncture Needles LotNo.11C After the earthquake

Nuclide	Result (Bq/kg)	Detection Limit (Bq/kg)
Iodine-131	Not detected	18
Caesium-134	Not detected	10
Caesium-137	Not detected	9
Caesium-136	Not detected	10

Method:

Gamma ray spectrometry

Y.HANAMOTO

Reviewed by

A handwritten signature in black ink, appearing to read 'Y. Hanamoto', written over a horizontal line.